09/05/2012 to 12/05/2012

Project Nbr(s)	PCN(s)	County(s)	Type of Work	Location	Tentative Letting Date
BRF 0063(30)96	00KT	Haakon	Deck Replacement, Approach Slabs, Approach Guardrail, Approach Pavement, Zone Paint & Integral Abutments	0.3 S of US14 Over the Bad River @ Midland	09/05/2012
P 0044(148)120	01R5	Jackson	Bridge Deck Overlay, Epoxy Deck Seal, Replace Bridge Rail and Asphalt Surfacing of Approaches	SD 44, 1.0 miles east of Interior over Johnson Creek & 5.7 miles east of the SD 73 Junction	09/05/2012
PH 8033(205)	01UB	 Hughes	Signing and Delineation	Various Roads in Hughes County	09/05/2012
IM 0294(61)121	02PC	Codington, Deuel, Hamlin	Replace Interstate Fence	I29 from MRM 150 to MRM 186 in the Watertown Area	09/05/2012
IM 0299(61)208	02PL	Roberts	Nonreinforced PCC Surfacing	I 29 S from the Jct. with US12 to north of the Peever Exit	09/05/2012
BRO 8052(53)	H079	Pennington	Structures and Approach Grading (2-12'x6' & 2-12'x4' Precast RCBC)	6.7 E of New Underwood (Co Hwy 1416) Over a Creek; 5.6 E of New Underwood (Co Hwy 1416) Over a Creek	09/05/2012
EM 0385(15)0	00D0	Fall River	Grading, Structure, PCC Surfacing, and Asphalt Concrete Resurfacing	US 385 from the Nebraska State Line north to the US 18 Junction and Structure 5 miles south of US18E over Horse Head Creek	09/19/2012
BRF 0050(86)407, BRF 0019(37)5, P 0010(89), P 0020(118)	00KR, 02RM, 03BU, 03BV	Clay, Deuel, Hamlin, Lincoln, Union	Bridge Repair and Bridge Painting	SD 19, SD 50, and Interstate 29 in Clay, Lincoln, Unioin, Deuel, and Hamlin Counties	09/19/2012
BRF 0020(98)334, BRF 0037(105)181, BRF 0212(154)306, BRF 0281(96)154	00LE, 00LG, 02RH, 039U	Brown, Spink	Scour Protection, Berm Repair & Column Repair	Various Locations in Brown and Spink Counties	09/19/2012
EM-NH 0014(159)230, 014 B-351, 1804-351	010L, I2HH, I2HK	Hughes	Concrete Pavement Repair, Crack and Seat PCC Pavement, Asphalt Concrete Resurfacing and Slipline Mainline Pipe	US 14 from Pierre to the east junction with US 83, US 14B south of US 14, and SD 1804 north of US 14	09/19/2012
P-PH 0087(11)73, P-PH 0089(07)58	01Q5, H031	Custer, Pennington	Cold Milling Asphalt Concrete and Asphalt Concrete Resurfacing	SD 87 from SD 89 to US 16, and SD 89 from US 16A to SD 87	09/19/2012

09/05/2012 to 12/05/2012

Project Nbr(s)	PCN(s)	County(s)	Type of Work	Location	Tentative Letting Date
P 0020(105)96, P 0073(52)177	022U, 022V	Meade, Perkins	Mill & AC Resurfacing, AC Surfacing	SD 20 from the N Jct. of SD73 to the S Jct. of SD73 & from the S Jct. of SD73 East 8.2 Mi. & SD73 from the west Jct. with US212 to the south Jct. with SD20	09/19/2012
PH 000S(277)	02P6	Regionwide	Guardrail Replacement	Various locations in the Rapid City and Pierre Regions	09/19/2012
IM 0903(96)174	02PB	Jones	Fence Replacement	Interstate 90 from MRM 174.5 to MRM 208.5	09/19/2012
P 0023(35)	03JM	Bon Homme, Yankton	Asphalt Concrete Crack Sealing	Various Routes in the Yankton Area	09/19/2012
P 0021(99)	03JN	Davison	Shoulder Repairs	SD 37 in the Mitchell Area	09/19/2012
NH 0014(187)333	03KF	Beadle	Culvert Replacement & Culvert Extension	US 14, 0.2 miles east of US 281, & 0.4 miles north of the south junction with US 281	09/19/2012
NH-ER 0081(96)112	03Q5	Kingsbury	PCC Pavement Repair	US81, Fm Approx. 4.6 Mi N of the Lake/Kingsbury/Brookings County Line N 2.4 Mi (MRM 112.3 to 114.7)	09/19/2012
P 0034(138)312	020A	Jerauld	Structure Replacement	SD34 - Fm Just E of Dakota Ave to 0.1 mile east of Dakota Ave in Wessington Springs	10/03/2012
P 0010(80)203	025Q	Campbell, McPherson	Mill & AC Resurfacing	SD10 from the south Jct. with US83 to Eureka	10/03/2012
PH 8014(32)	02AP	Clay	Signing & Delineation	Various County, City, and Township Roads in Clay County	10/03/2012
PH 000S(221)	02C6	Regionwide	Install Rumble Strips	Various Locations on the State System in the Mitchell Region	10/03/2012
P 0037(115)128	02FA	Beadle	Grading & PCC Surfacing; Lighting	SD37 Fm 15th St NW to 27th St NW in Huron	10/03/2012

09/05/2012 to 12/05/2012

Project Nbr(s)	PCN(s)	County(s)	Type of Work	Location	Tentative Letting Date
IM 0294(63)123	02Q1	Brookings, Moody	Remove and Replace PCC Surfacing, Epoxy Chip Seal, Approach Slabs, & Approach Slab Joint Modification	I29 SBL from the Big Sioux River to south of the SD 30 junction & Str. 1.1 N of US14B Over Six Mile Creek; 1.0 S of Brookings Co over Big Sioux River	10/03/2012
P 0034(155)341	037J	Miner, Sanborn	Mill & AC Overlay	SD34 from the east Jct.with SD37 to the Sanborn/Miner County Line & From West of Roswell to the East Jct. With SD25	10/03/2012
IM 0902(148)112	021B	Pennington	Remove & Replace PCC	I90- EBL, Fm west of the Jct. with US14 to Just E of Exit 121 (Big Foote Road)	10/17/2012
PH 8027(30)	02AQ	Gregory	Signing & Delineation	Various County, City, & Township Roads in Gregory County	10/17/2012
PH 8056(11)	02AR	Sanborn	Signing & Delineation	Various County, City, & Township Roads in Sanborn County	10/17/2012
P 0065(15)215	0377	Corson	Mill & AC Overlay	SD65 from north of the Grand River to the Jct. with US12	10/17/2012
P 0073(61)53, P 0073(55)37, P 0073(66)37	022X, 6955, 03KA	Bennett, Jackson	Mill & AC Resurfacing	SD73 from north of the Jct. with SD44 to Kadoka	11/07/2012
NH 0212(159)367	023J	Codington	Mill & PCCP	US212, US212 E & US212 W from west of Lake Kampeska to west of the Jct. with SD20 in Watertown	11/07/2012
IM 0901(174)10	0357	Lawrence	Remove and Replace Concrete & Epoxy Chip Seal, Rail Replacement, Joint Modification and Approach Slabs on Structures & Lighting on Exit 12	I90, EBL, from the US85N Exit to E of the US85S Exit, & Strs 0.3 W of US85N Exit (Mainline & Ramp Stirs); 0.7 W & 1.0 E of US14A; & 1.5 W of US85S Exit.	11/07/2012
NH 0018(119)242	0018	Tripp	Mill & PCCP Resurfacing	Fm W of SD53 to the End of the Div Hwy in Winner	11/21/2012
P 1804(12)251	02V1	Hughes	Slide Repair and Subgrade Stabilization	SD 1804, approximately 1.5 miles north of US 14 near Pierre	11/21/2012

09/05/2012 to 12/05/2012

Project Nbr(s)	PCN(s)	County(s)	Type of Work	Location	Tentative Letting Date
NH 0016(81)50	0362	Pennington	Mill & AC Overlay; Median Improvements	US16 E & W from east of the Keystone Wye to southwest of Rapid City	11/21/2012
BRF 0281(93)85, BRF 0034(144)317, BRF 1804(11)113	01S5, 01S6, 01S7	Aurora, Charles Mix, Jerauld	Epoxy Deck Seal, Deck Overlay & Replace Bridge Rail	1.3 S County Line over Firesteel Ck; 1.4 W Jct US 281 over Firesteel Ck; & 5.9 S Jct SD 44 & SD 50 over Platte Ck & 7.1 S Jct SD 44 & SD 50 over a Ck	12/05/2012
P 0085(77)25, P 0385(45)87	022G, 02R7	Lawrence, Pennington	Mill & AC Resurfacing	US385 from 1.5 N of the Jct. with US16 to Pactola Reservoir and US385 from 4 mi N of the Jct. with SD44 to south of Lead/Deadwood	
NH 0014(183)331	023G	Beadle	Mill & AC Resurfacing	US14 from south of Wolsey to east of the Jct. with US281	12/05/2012
P 0046(47)356	025D	Clay	Mill & AC Resurfacing (Exception MRM 356.61 to 356.670) & Extend Culvert	SD46 - Fm E of the Vermillion River Str to W of the Jct. with I29	12/05/2012
PH 000S(229)	02CE	Regionwide	Install Rumble Strips	Various Locations on the State System in the Pierre Region	12/05/2012
IM 0905(100)308	02PJ	Aurora, Davison	Replace Interstate Fence	I90 - Yankton Area	12/05/2012
NH 0012(166)354	035V	Day, Roberts	PCC Overlay and Remove & Replace PCC Pavement	US12 EBL fm E of Waubay to E of the Main Entrance Into Summit	12/05/2012